November-08-13	3 2:22:30 PA	<u>И</u> : <del>_</del> : : :											
Item ID: Revision ID:	D3262-043	*		Accept	*N90	0040	1100	<b>)</b> *	Setup	Start	*N	S1*	
	Canister Asse	embly								Stop	*N:	S2*	
Start Date:	11/08/13	Start Qty: 3.00	*3*		Cust Iten	n ID:							
Required Date:	11/15/13	<b>Req'd Qty:</b> 3.00	*3*		Custome	r:							
Reference:													
Approvals:	Process Pla	an:	Date:	Tooling:		Date:		J	Run	Start	*N	R1*	
	QC:		Date:	_ SPC (Y/N):		Date:				Stop	*N	R2*	
Sequence ID/ Work Center II	)	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp	
Draw Nbr	Rev	vision Nbr											
D3262	Е		_										
100			uminum rod Batch: MD]	165 0.00	-							۸.	
*100*		Large Fab						(	3)	13-1	1.11	10	
Large Fab		Memo		0.00							, <del>1</del>		-
Large Fab		Weld canis	iter assembly as per Dwg D	3262 using DT8739 to al	lign fittings								_
		'000 I	OCIONA Facian Walds	0.00								71	8
110		QC9- Inspect Visual per	r QSI004- Fusion Welds	0.00				<b>つ</b>	_	,	13-11-		
*11 <b>0</b> *		Mama	•	0.00				3	9		1371	<u> </u>	
Quality Control		Memo	r <sub>en</sub>	••••									
		, in the second second										K	ÃS
120		QC5- Inspect part comp	pleteness to step on W/O	0.00			,	7			13-11	112	18
*120*		Memo		0.00				<u> </u>	0		13-11	-/3	-
Quality Control			est as ner Dwg D3262										

November-08-13 2:22:50 PM

Revision ID:	D3262-043 Canister Asse	mbly		Accept			*N900040100				Setup Star Stop	I VI -	*NS1* *NS2*	
Start Date: Required Date: Reference:	11/08/13	Start Qty: 3.00 Req'd Qty: 3.00	*3* *3*			Custo		D:			G.			
Approvals:	Process Pla	an:	Date:	Tooling:			Da	ate:		ŀ	Run Star Stop	I <i>Z</i> I	R1*	
	QC:		Date:	SPC (Y/	'N):		_ Da	ate:			Stop	*N	R2*	
Sequence ID/ Work Center II	<b>D</b>	Operation Description			p/ Hours	Too	l ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	
*130 *130* HandFinish Hand Finishing		Chemical Conversion Co  Memo	at per QSI005 4.1	0.00						2		CF (3-11	?b =	₹
*140 *140 Powdercoat  Powder Coating		White Gloss(Ref.4 3.5.1)  Memo  ****Ensure  START TIM  OVEN TEM  FINISH TIM	to mask ####ds ### E: PERATURE:	0.00						2	<u> </u>	<u>B-11-19</u>	?	DA\$  34  98
*150 *150* QC Quality Control		QC3- Inspect Part Finish  Memo		0.00	DAS 27 9-89 /3-//	19				\$				_

banda

DQA:	Las	4	Date:	13/12 1B/11	/ -		WORK ORDER NON-CONFORMANCE / UPDATE  Work Order update only							
Work Order: 199064				DISPOSITION			AGAINST	] Engineering						
Part No. <u>D3262-043</u> NCR No. <u>13-3255</u>				<u>3</u>	Rework Scrap  Vse-as-is Suspected Unapproved	Scrap X Machining Small Fab Use-as-is Thermoforming Finishing			X Rec/Store/Packaging Other					
Root Cause	C	ate	Step	Qty	Descr	iption of work order update or non-conformance		nitial ief Eng	Action Description	Sign & Date	Verification	QC Inspector		
Design Doc/Data Equip/Tooling Handling/Pre Material Operator Offset/Setup Process Supplier Training Transport Unapproved	<u>x</u> 1	[.,/14	# 30	*1	ACID	The Consister.  Dropeo after etching.  Miss bandling of Ponts	(a)	) ,2647 3/11/14	Due to other issus.  + Fear of Failux in Reald.  Pant Scrop/Destry. No Replac.	13/11/14		5 13/11/14 012042		
							FAI	JLT CA	regory					
Landin	ıg Gea	•				General	_				_	7		
Centre Not Concentric Cracks Crimp/Kink/Ripple/Wave			Bend BOM/Route Broken/Damage/Defect Burrs Contamination	-	Grain Hardwa Inspect	Program  are  ion Incomplete/Unqualified  tions Incomplete/Unclear	Outside Dir Over/Unde Part Incorre Part Lost/M Part Movee	r tolerance eci 1issing	Pressure/Forced Set-up Temperature/Cure Weld Wrong Stock Pulled					
	Crushing Heat Treat				Countersink Cut Too Short		Misali Mislab	gned/off center eled	Positioned	Positioned Wrong Power Loss/Surge  / Other				
	_	•	Strip in	Tube		Drawing	_	Misrea			misshanolij w Parts / Part shaped			
	_	rks/Ch			<b> </b> -	Drill Holes	-	Off-set	Calibration	apt of 6	atitud employees hands.			
Turning Sequence Wave/Twist in Tube			Finish Fit/Function	$\vdash$	4	Sequence								

Work	Order	ID	109064
------	-------	----	--------

Quality Control

Memo

\*109064\* Page 3 November-08-13 2:22:50 PM Accept D3262-043 \*N900040100\* Item ID: Setup Start **Revision ID:** Canister Assembly Item Name: Start Qty: 3.00 Start Date: 11/08/13 **Cust Item ID:** Required Date: 11/15/13 Reg'd Oty: 3.00 **Customer:** Reference: Run Process Plan: \_\_\_\_\_ Date: \_\_\_\_ Tooling: Date: **Approvals:** Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Reject Reject Set Up/ Tool ID Tool # Plan Accept Insp. Number Stamp Work Center ID Code Qty Qty Description **Run Hours** 0.00 160 Identify as per dwg & Stock Location: \*160\* Packaging Memo 26 Packaging 170 QC21- Final Inspection - Work Order Release 0.00 \*170\* 0.00 QC

## Picklist Print

November-08-13 2:22:50 PM

Work Order ID:

109064

Parent Item:

Comments:

D3262-043

Parent Item Name:

Canister Assembly

IPP rev A 10.01.19 new issue EC verified by: DD 10.05.10 verified : EC

IPP Rev:B as per ECN10-571 DD

**Start Date:** 11/08/13

Required Date: 11/15/13

Page 1

Start Qty: 3.00

Required Qty: 3.00


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measu		Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3262-1		Manufactured	No			100	Each	6.0000	1	3	(2)	13.11.11	PD
Tube									(*************************************			3.11.11	ייייי
				<b>Location</b>		Loc Qty		Loc Code					
				LG002	_	6							
				$\boxed{106}$	183	6				<u> </u>			
D3262-5		Manufactured	No			100	Each	13.0000	2	6	(1)		0N
Cap									F-74-4		<u> </u>	3-11-11	1)
				<b>Location</b>		Loc Qty		Loc Code					
				LG002		1							
•				747	24	1							
				WA003		12							
				106		6				<u> </u>			
				107		4							
				953	53	2							


QTY -041 ITEM P/N DESCRIPTION D3262-041 CANISTER ASSEMBLY TUBE D3262-1 D3262-3

D

С

2





**D3262-041 CANISTER ASSEMBLY** 

8

D

NOTES:
1) MATERIAL: N/A
2) FINISH: CHEMICAL CONVERSION COAT PER QSI 005 4.1
POWDER COAT ASSEMBLY WHITE (4.3.5.1) PER DART QSI 005 4.3
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.00 TO 0.010 MAX
6) IDENTIFICATION: IDENTIFY WITH DART P/N "D3262-041" AND B/N USING FINE POINT PERMANENT INK MARKER
7) WEIGHT: 2.51 lbs
8) LIQUID PENETRANT INSPECT PER ASTM F1417 LEVEL 1 OR

9) LIQUID PENETRANT INSPECT PER ASTM E1417 LEVEL 1 OR PRESSURIZE TO 10 psi AND SUBMERGE UNDER WATER TO CHECK FOR LEAKS

25.00									
REV.	DESCRIPTION	BY	DATE						
Α	NEW ISSUE	RF	04.05.06						
В	ADD PRESSURE TESTING OPTION	MB	05.02.14						
С	Ø5.165 WAS Ø5.190	RF	06.08.31						
D	ADD D3262-043/-5 (ZN B5-2; B5-5); REVISE DIMENSIONS TO EQUAL TOOL DIMENSIONS (ZN B2-4; C2-4) PER CAR 09-004	RF	09.12.30						
E	0.25 WAS 0.45 (ZNC7-4, C7-5); 0.13 WAS 0.33 (ZN 87-4, B7-5); ADD DIMENSION (ZN B1-4, D1-5, B1-5)	RF	10.05.03						

DESIGN RF		DART AEROSPACE LT	D
DRAWN	RF	HAWKESBURY, ONTARIO, CANAD	_
CHECKED	1	DRAWING NO.	REV. E
MFG. APPR.	ge/		SHEET 1 OF 5
APPROVED	10	TITLE	SCALE
DE APPR.	-#	FUEL PURGE CANISTER	NTS
DATE 10.0	5 03	COPYRIGHT © 2004 BY DART AEROSPACE THIS DOCUMENT IS PROVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS IS	


3


7

5

8

ITEM	QTY -043	P/N	DESCRIPTION	
	Х	D3262-043	CANISTER ASSEMBLY	Ξ
1	1	D3262-1	TUBE	
2	2	D3262-5	CAP	





## **D3262-043 CANISTER ASSEMBLY**


RELEASED 2010 -05- 95 D

NOTES:
1) MATERIAL: N/A
2) FINISH: CHEMICAL CONVERSION COAT PER QSI 005 4.1
2) FINISH: CHEMICAL CONVERSION COAT PER QSI 005 4.1
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.05 TO 0.010 MAX
6) IDENTIFICATION: IDENTIFY WITH DART P/N "D3262-043" AND B/N USING FINE POINT PERMANENT INK MARKER
7) WEIGHT: 2.50 lbs
8) LIQUID PENETRANT INSPECT PER ASTM E1417 LEVEL 1 OR
PRESSURIZE TO 10 psi AND SUBMERGE UNDER WATER TO CHECK FOR LEAKS
9) WELD CAPS WITH 3/4-16 TAP TOP HOLE IN LINE WITH 9/16-18 TAP BOTTOM HOLE

7

8

DESIGN RF DRAWN RF		DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA					
CHECKED	15	DRAWING NO.	REV. E				
MFG. APPR.	91	D3262	SHEET 2 OF 5				
APPROVED	14	TITLE	SCALE				
DE APPR.	4	FUEL PURGE CANISTER	NTS				
DATE 10.0	5.03	COPYRIGHT © 2004 BY DART AEROSPACE LTD THIS DOCUMENT IS PRIVATE AND COMPRENT, AND IS SUPPLIED ON THE DOPRESS CONCIDENT THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COMPLINEATIZED TO ANY TOTION PORTION WITHOUT WITHOUT PURPOSES OF KNOWN DAYS ASSOSPACE LTD.					



D3262-1 TUBE

NOTES: 1) MATERIAL: 6061-T6 OR 6061-T62 ALUMINUM TUBING, 5.00 OD x 0.125 WALL PER WW-T-700/6 OR AMS 4080 OR AMS 4082 OR QQ-A-200/8 OR QQ-A-225/8 REF. DART SPEC. M6061T6T5.000W.125

REF. DART SPEC. M6061T6T5.000W.125
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: NONE
7) WEIGHT: 1.96 lbs
8) PART IS SYMMETRICAL ABOUT CENTERLINE

DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA DESIGN DRAWN RF CHECKED DRAWING NO. REV. E D3262 MFG. APPR. SHEET 3 OF 5 APPROVED TITLE SCALE **FUEL PURGE CANISTER** DE APPR. NTS COPYRIGHT @ 2004 BY DART AEROSPACE LTD


NES DOQUMENT S PRINTE ARE COMPOSITING, MIGHT SERVICED ON THE EXPRESS COMMON THAT IT IS MUST TO SELVED FOR MAY THROUGH OF COMPOSITING COMMON THE TO THE OWN PRESDIVENEUT WHITTON PROMOSOUR PROMOMENT ARROPMENT. TO DATE 10.05.03

3


2

£ - 0.25 Ø0.875 2 PL \$\displaystyle{4} \phi 5.005 +0.010 \\ -0.000 R0.063 TYP 0.13 TYP 0.070 x 45° CHAMFER 0.080 TYP

SECTION A-A C5-4



D3262-3 CAP



1) MATERIAL: 6061-T6/T651 ALUMINUM BAR
PER QQ-A-200/8 OR QQ-A-225/8
REF. DART SPEC. M6061T6B
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: ENGRAVE 'DART' LOGO AS SHOWN USING 0.75 HIGH x 0.010 DEEP
' (MANY) I ETTERS MATHETON DADING OF 6 25 MIN

(MAX) LETTERS WITH TOOL RADIUS OF 0.25 MIN 7) WEIGHT: 0.28 lbs 8) PART IS SYMMETRICAL ABOUT CENTERLINE

DESIGN	RF	DART AEROSPACE	TD
DRAWN	RF	HAWKESBURY, ONTARIO, CANA	
CHECKED	15	DRAWING NO.	REV. E
MFG. APPR.	9/	D3262	SHEET 4 OF 5
APPROVED	1H	TITLE	SCALE
DE APPR.	-41-	FUEL PURGE CANISTER	NTS
DATE 10.0	5.03	COPYRIGHT © 2004 BY DART AEROSPAC THIS DOCUMENT IS PRIVATE AND CONTRIBUTION AND IS SUPPLIED ON THE EXPR	SETS TANT MORTONCO 22

7

8


NOTES:

6

5


D


С



D3262-5 CAP

NOTES:
1) MATERIAL: 6061-T6/T651 ALUMINUM BAR
PER QQ-A-200/8 OR QQ-A-225/8
REF. DART SPEC. M6061T6B
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: 0.005 TO 0.010 MAX
6) IDENTIFICATION: ENGRAVE 'DART' LOGO AS SHOWN USING 0.75 HIGH x 0.010 DEEP
(MAX) LETTERS WITH TOOL RADIUS OF 0.25 MIN
7) WEIGHT: 0.27 lbs 7) WEIGHT: 0.27 lbs 8) PART IS SYMMETRICAL ABOUT CENTERLINE





DESIGN	RF	DART AEROSPACE	TD
DRAWN	RF	HAWKESBURY, ONTARIO, CANA	
CHECKED	<b>\$</b>	DRAWING NO.	REV. E
MFG. APPR.	91	D3262	SHEET 5 OF 5
APPROVED	140	TITLE	SCALE
DE APPR.	#	FUEL PURGE CANISTER	NTS
DATE 10.0	5.03	COPYRIGHT © 2004 BY DART AEROSPAC THIS DOCUMENT IS PRIVATE AND COMPONING AND IS SUPPLIED ON THE GOPE NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMANICATED TO ANY D	SS CONDITION THAT IT IS

3

8

D

7

5

DRILL THRU Ø0.516

1.63

DRILL THRU Ø 0.688 (11/16 DRILL), TAP HOLE 3/4-16 UNF-3B

PER MIL-S-8879

3.25 REF

(33/64 DRILL), TAP HOLE

9/16-18 UNF-3B

PER MIL-S-8879

2

D